
Resistograph Not Connected to This System

Platform

Generic Collect

Summary



Description

The above error can occur when the resistograph is not connected to the Toughbook via Bluetooth.

Troubleshooting

- 1. Reboot the Toughbook and try to connect again
- 2. If that does not work, contact Alden Support

